# maxon EC motor iron-cored winding Technology - short and to the point

#### Characteristics of maxon EC flat motors and EC-i motors

- Brushless DC motor
- Long service life
- Flat design for when space is limited
- Comparatively high inertia
- Motor characteristics may vary from
- the strongly linear behaviour Hall sensor signals utilizable for simple
- speed and position control - Winding with iron core and several teeth per phase in the stator
- Low detent torque
- Good heat dissipation, high overload capacity
- Multipole Neodymium permanent magnet
- Smaller commutation steps

### Characteristics of maxon EC flat motors

- Attractive price/performance ratio
- High torques due to external, multipole rotor Excellent heat dissipation at higher speeds
- thanks to open design Speeds of up to 20000 rpm
- rotor with 1 pole pair
- Characteristics of the maxon EC-i program
- Highly dynamic due to internal,
- multipole rotor
- Mechanical time constants below 3 ms
- High torque density
- Speeds of up to 15000 rpm

# **Bearings and service life**

The long service life of the brushless design can only be properly exploited by using preloaded ball bearings.

- Bearings designed for tens of thousands of hours
- Service life is affected by maximum speed, residual imbalance and bearing load

## **Program**

- EC flat motor
- with Hall sensors
- sensorless
- with integrated electronics

### **1** Flange

- 2 Housing
- 3 Laminated steel stack
- 4 Winding
- **9** Permanent magnet
- 6 Shaft
- Print with Hall sensors
- 8 Ball bearing
- Spring (bearing preload)

# **Electronical commutation**

#### **Block commutation**

#### Properties of block commutation

- Relatively simple and favorably priced electronics
- Controlled motor start-up
- High starting torques and accelerations possible
- determined with block commutation.

Block commutation Signal sequence diagram for the Hall sensors

11

Supplied motor voltage (phase to phase)

III IV V

120 180 240

VI

300 360

#### **Possible applications**

- Highly dynamic servo drives
- Start/stop operation
- Positioning tasks

Conductive phases

U1-2

U2-3

U3-1

Rotor position

Hall sensor 1 Hall sensor 2 Hall sensor 3

## Sensorless block commutation

The rotor position is determined using the progression of the induced voltage. The electronics evaluate the zero crossing of the induced voltage (EMF) and commute the motor current after a speed dependent pause (30° after EMF zero crossina).

The amplitude of the induced voltage is dependent on the speed. When stalled or at low speed, the voltage signal is too small and the zero crossing cannot be detected precisely. This is why special algorithms are required for starting (similar to stepper motor control). To allow EC motors to be commuted without sensors in a  $\Delta$  arrangement, a virtual star point is usually created in the electronics.

### Properties of sensorless commutation

- No defined start-up
- Not suitable for low speeds
- Not suitable for dynamic applications

#### Possible applications

- Continuous operation at higher speeds
- Fans, pumps



The commutation angle is based on the length of a full commutation sequence (360°e). The length of a commutation interval is therefore 60°e.

The values of the shaft position can be calculated from the commutation angle divided by the number of pole pairs.

Rotor position is reported by three built-in Hall sensors which deliver six different signal combinations per commutation sequence. The three phases are powered in six different conducting phases in line with this sensor information. The current and voltage curves are block-shaped. The switching position of every electronic commutation lies symmetrically around the respective torque maximum.

- The data of the maxon EC motors are